



US Motor Works, LLC
 14722 Anson Avenue
 Santa Fe Springs, Ca 90760, USA
 Tel: 562-404-0488
 Fax: 562-404-8770
 info@usmotorworks.com
 www.usmotorworks.com

CERTIFIED • OEM QUALITY • RELIABILITY

MARKETING COMMUNICATION NEW PRODUCT BULLETIN- NEW FUEL PUMP MODULES

Date of Release: June 29, 2018

Availability: In Stock



USEP8420M
 01-02 Kia-Rio 1.5L
OEM # 0K32A-13-35ZA



USEP8531M
 07-09 Mercedes-Benz C230, C350,
 CLK350, CLK500 2.5L, 3.5L, 5.0L
OEM # 209-470-0194



USEP8586M
 03-08 Mazda 6 3.0L
OEM # AJ80-13-35ZA



USEP8633M
 001-02 Volvo S60, S80, V70
 2.3L, 2.4L, 2.8L, 2.9L
OEM # 30636490



USEP8637M
 02-05 Hyundai-Sonata,
 02-04 KIA-Optima 2.4L
OEM # 31110-38260



USEP8657M
 05-08 Acura-MDX,
 Honda-Pilot 3.5L
OEM # 17045-S3V-A01



USEP8655M
 05-06 Honda CR-V 2.4L
OEM # 17045S9AA00



USEP8660M
 04-06 Nissan Altima 2.5L, 3.5L
OEM # 17040-8J020



USEP8588M
 03-08 Mazda 6 2.3L
OEM # L390-13-35ZB

Please visit www.usmotorworks.com for detailed applications or contact customer service for further information.





CERTIFIED • OEM QUALITY • RELIABILITY

US Motor Works, LLC
 14722 Anson Avenue
 Santa Fe Springs, Ca 90760, USA
 Tel: 562-404-0488
 Fax: 562-404-8770
 info@usmotorworks.com
 www.usmotorworks.com

**NEW PRODUCT BULLETIN -
 NEW FUEL PUMP MODULES**

Year	Make	Model	Engine Liters	Part Number
2001	KIA	RIO	1.5L	USEP8420M
2002	KIA	RIO	1.5L	USEP8420M
2007	Mercedes-Benz	C230	2.5L	USEP8531M
2006	Mercedes-Benz	C350	3.5L	USEP8531M
2007	Mercedes-Benz	C350	3.5L	USEP8531M
2006	Mercedes-Benz	CLK350	3.5L	USEP8531M
2007	Mercedes-Benz	CLK350	3.5L	USEP8531M
2008	Mercedes-Benz	CLK350	3.5L	USEP8531M
2009	Mercedes-Benz	CLK350	3.5L	USEP8531M
2003	Mercedes-Benz	CLK500	5.0L	USEP8531M
2004	Mercedes-Benz	CLK500	5.0L	USEP8531M
2005	Mercedes-Benz	CLK500	5.0L	USEP8531M
2006	Mercedes-Benz	CLK500	5.0L	USEP8531M
2003	Mazda	6	3.0L	USEP8586M
2004	Mazda	6	3.0L	USEP8586M
2005	Mazda	6	3.0L	USEP8586M
2006	Mazda	6	3.0L	USEP8586M
2007	Mazda	6	3.0L	USEP8586M
2008	Mazda	6	3.0L	USEP8586M
2003	Mazda	6	2.3L	USEP8588M
2004	Mazda	6	2.3L	USEP8588M
2005	Mazda	6	2.3L	USEP8588M
2006	Mazda	6	2.3L	USEP8588M
2007	Mazda	6	2.3L	USEP8588M
2008	Mazda	6	2.3L	USEP8588M
2002	Hyundai	Sonata	2.4L	USEP8637M
2003	Hyundai	Sonata	2.4L	USEP8637M
2004	Hyundai	Sonata	2.4L	USEP8637M
2005	Hyundai	Sonata	2.4L	USEP8637M
2002	KIA	Optima	2.4L	USEP8637M
2003	KIA	Optima	2.4L	USEP8637M
2004	KIA	Optima	2.4L	USEP8637M

Please visit www.usmotorworks.com for detailed applications or contact customer service for further information.





CERTIFIED • OEM QUALITY • RELIABILITY

US Motor Works, LLC
 14722 Anson Avenue
 Santa Fe Springs, Ca 90760, USA
 Tel: 562-404-0488
 Fax: 562-404-8770
 info@usmotorworks.com
 www.usmotorworks.com

**NEW PRODUCT BULLETIN -
 NEW FUEL PUMP MODULES**

Year	Make	Model	Engine Liters	Part Number
2006	Acura	MDX	3.5L	USEP8657M
2005	Honda	Pilot	3.5L	USEP8657M
2006	Honda	Pilot	3.5L	USEP8657M
2005	Honda	CR-V	2.4L	USEP8655M
2006	Honda	CR-V	2.4L	USEP8655M
2004	Nissan	Altima	2.5L	USEP8660M
2005	Nissan	Altima	2.5L	USEP8660M
2006	Nissan	Altima	2.5L	USEP8660M
2006	Nissan	Altima	3.5L	USEP8660M
2001	Volvo	S60	2.3L	USEP8633M
2002	Volvo	S60	2.3L	USEP8633M
2001	Volvo	S60	2.4L	USEP8633M
2002	Volvo	S60	2.4L	USEP8633M
1999	Volvo	S80	2.8L	USEP8633M
2000	Volvo	S80	2.8L	USEP8633M

